Oil Field Environmental Incident Summary

Responsible Party: BAYTEX ENERGY USA LTD
Well Operator: BAYTEX ENERGY USA LTD

Well Name: MARJORIE 6-7-161-97H 1XP

Field Name: WHITEAKER Well File #: 22781

Date Incident: 7/15/2014 Time Incident: 06:00 Facility ID Number:

County: DIVIDE Twp: 162 Rng: 97 Sec: 31 Qtr: SE SW

Location Description:

Submitted By: Randy Verret Received By:

Contact Person: Randy Verret

600 17TH ST STE 1600 SOUTH DENVER, CO 80202-5419

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:0.5 MileDistance Nearest Water Well:0.5 Mile

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - On Facility Site Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine 75 Barrels 60 Barrels 60 barrels

Other

Description of Other Released Contaminant:

Not Applicable

Inspected: Written Report Received: 7/13/2016 Clean Up Concluded: 7/15/2014

Risk Evaluation:

Minimal

Areal Extent:

Wholly within secondary containment

Potential Environmental Impacts:

Minimal- produced water in containment

Action Taken or Planned:

Pumper spotted spill and immediately closed tank valve. Vacuum truck immediately dispatched to begin fluid removal. Once liquid is evacuated any contaminated soil will be removed & new gravel placed as needed. Left voicemail for NDIC field inspector (Marc Binns). Will review loading procedures with hauler.

Wastes Disposal Location: Liquids will be injected into nearby Anderson SWD #11-17 & solids will be excavated & trucked to an approved landfill for disposal.

Agencies Involved:

Updates

Date: 7/17/2014 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a tank overflow, remained on location within the diking according to the report. NDIC retains oversight.